

BILL OF QUANTITIES


UNIVERSITY OF RIZAL SYSTEM

(Agency)

Project Title: Repair & Improvement of Administration Building at URS Tanay Campus

Work Duration: 90 Calendar Days

Unit	Item Description	Quantity	Unit Cost	Total Cost
<i>lot</i>	<i>MOBILIZATION</i>	<i>1</i>		<i>P</i>
<i>sq.m</i>	<i>DEMOLITION WORKS</i>	<i>396</i>		
	<i>CEILING WORKS</i>			
<i>pcs</i>	<i>Hardiflex 1/4x4x8</i>	<i>186</i>		
<i>pcs</i>	<i>Metal Furring</i>	<i>1165</i>		
<i>box</i>	<i>Blind Rivets</i>	<i>32</i>		
<i>pcs</i>	<i>Drill bits</i>	<i>15</i>		
<i>pcs</i>	<i>Tox & Screw big</i>	<i>420</i>		
	<i>PAINTING WORKS</i>			
<i>kg/s.</i>	<i>Patching Compound</i>	<i>125</i>		
<i>Tin/s.</i>	<i>Flat Latex Paint</i>	<i>18</i>		
<i>Tin/s.</i>	<i>Semi gloss Latex Paint</i>	<i>16</i>		
<i>ltr/s.</i>	<i>Acry Color Raw Seana</i>	<i>7</i>		
<i>pc/s.</i>	<i>Paint Brush #2</i>	<i>8</i>		
<i>set</i>	<i>Paint Roller w/ pan</i>	<i>6</i>		
<i>tube</i>	<i>Sealant</i>	<i>20</i>		
<i>gal/s.</i>	<i>ODE -WHITE</i>	<i>4</i>		
<i>gal/s.</i>	<i>Epoxy Primer</i>	<i>2</i>		
<i>gal/s.</i>	<i>Paint Thinner</i>	<i>3</i>		
<i>pc/s.</i>	<i>Paint Brush #3</i>	<i>6</i>		
	<i>ELECTRICAL WORKS</i>			
<i>sets</i>	<i>Down LED Light</i>	<i>46</i>		
<i>pcs</i>	<i>Junction Box</i>	<i>45</i>		
<i>pcs</i>	<i>PVC Pipe Orange 1/2</i>	<i>135</i>		
<i>roll</i>	<i>Electrical Tape Big</i>	<i>35</i>		
<i>box</i>	<i>THHN #12</i>	<i>6</i>		
<i>set</i>	<i>3Gang Switch</i>	<i>8</i>		
<i>set</i>	<i>Project Signage 8x8 70dpi</i>	<i>2</i>		
	<i>*** Nothing follows ***</i>			
			<i>Material Cost</i>	
			<i>Labor Cost</i>	
			<i>PROFIT</i>	
			<i>OCM</i>	
			<i>VAT</i>	
			TOTAL	924,767.42






SCOPE OF WORKS:

1. Removal and Replacement of Ceiling Joist and Ceiling Board at ground floor (areas to replace Lobby, Cahiers's Area, Registrars Area and Library with leaking area only)
2. Painting Works
3. Application of Sealant for the leaking roofing
4. Replacement of all Electrical Fixtures and wiring
5. Cleaning and Clearing works

Note:

6. Conduct Inspection on site before submitting the BID PRICE
7. Follow lighting set up and replacement into draft light

This portion only at the Library area to be repair the Ceiling

PROJECT TITLE: PROPOSED REPAIR & IMPROVEMENT OF ADMINISTRATION BLDG PH II <small>Tampu Campus</small>	Reviewed and Submitted by:  NELSON S. GALES, Ed. D. Director, General Services
	Recommending Approval
Design & Drawn by:  CRISTOPHER N. VIVAS Head, Physical Facilities Repair and Maintenance	Approved by: NANCY T. PASCUAL, Ed. D. VICE PRESIDENT FOR ADMINISTRATION AND FINANCE
Checked and Certify Correct by:  VON CYRELL D.L. SAN JOSE, RCE Engineer, UPFDU	Approved by: MARITA R. CANAPI, Ed. D. PRESIDENT

GROUND FLOOR

