

Republic of the Philippines UNIVERSITY OF RIZAL SYSTEM

Pililla Rizal (02) 8539-9942-44







JOB PROPOSAL

August 02, 2022

DR. RENATO F. DE LEMON

Vice President for Administration and Finance University of Rizal System

Sir:

In connection with the activities at the URS Pililla Campus and will full understanding of the scope of the activities described below, we (I) quote our price for labor in the amount of: Php*

NAME OF PROJECT: LABOR COST ESTIMATE FOR THE REPAIR OF THREE (3) **BUILDINGS IN URS PILILLA**

SCOPE OF WORK:

- 1. Ceiling and Painting of Science Laboratory
- 2. Ceiling and Painting of OSDS Building
- 3. Metal Trusses, Ceiling and Painting of COB Extension

There is no employer/employee relationship between the University and the contractor and the University shall not answerable to any damage or injury to workers and materials.

We (I) propose to complete the above activities within 21 days from the receipt of Notice to Proceed.

Bidders Name and Signature Witness to Canvass

Note: Actual inspection in the area of the project is required.



"Kurturing Comorrow's Koblest"

Republic of the Philippines UNIVERSITY OF RIZAL SYSTEM

Province of Rizal

University of Physical Sacilities Development Office

LABOR COST ESTIMATE FOR THE REPAIR OF THREE (3) BUILDINGS IN URS PILILLA								
		Pililla Ca	mpus					
		BILL OF QU		S				
ITEM	WORK DESCRIPTION	QTY	UNIT	UNIT COST (P)		COST		TOTAL (D
		QII		MATERIAL	LABOR	MATERIAL	LABOR	TOTAL (P)
A.	SCIENCE LABORATORY							
	Ceiling and Painting Works (Labor)	1	Lot					
1.00	Foreman	12.00	days					
4.00	Skilled	12.00	days					
3.00	Labor	12.00	days					
В.	OSDS BUILDING	1	Lot					
	Ceiling and Painting Works (Labor)							
1.00	Foreman	8.00	days					
4.00	Skilled	8.00	days					
3.00	Labor	8.00	days					
C.	COLLEGE OF BUSINESS (EXTENSION)	1	1.4					
<u> </u>	Metal Trusses, Ceiling, and Painting (Labor)		Lot					
1.00	Foreman	6.00	days					
4.00	Skilled	6.00	days					
3.00	Labor	6.00	days					
18.00	Scaffolding	10.00	days					
						TOTAL PRO	JECT COST	
						TOTALTRO	0201 0001	